

(Attic 3rd floor)
Room 302

The attic of the Oakland's property is facing a strong level of deterioration. For this report, the attic is known as room 302. As the days progress, and different temperatures persist, natural deterioration will continue for this entire property. The attic was smaller in size and it was very warm compared to other rooms that were located on the first and second levels. The attic contained household items were scattered in every direction. However, things that were visible were recorded for this report.

Windows

To the west of the room two small windows are installed. The window to the north (W-W-2) measures $24 \frac{2}{4} \times 30 \frac{1}{2}$, it has a shallow trim of $1 \frac{1}{8}$ (*see figure 1*). A wooden toggle was found on W-W-2 to hold cement in place attached a hand wrought nail. There is also a simple trim that outlines the window (W-W-2), it was metered upper cornices and butted to seal pieces that extend $2 \frac{1}{2}$ beyond the window frame on both sides (*see figure 2*). The window to the south (W-W-1) measures to $28 \frac{7}{8} \times 30 \frac{3}{4}$, this window's shallow trim measures to $1 \frac{1}{4}$. Both windows are inconsistent with window measurements from the first and second floors. The windowsills of both windows carried traces of green deteriorating paint.



(Figure 1, W-W-2)



(Figure 2, W-W-1)

Nails

Various nails were spotted throughout the attic that may have been placed there for hanging articles of clothing or have come loose to natural wear. After examination the nails seem to not be hand made.

Walls

The walls of the attic are wooden panels that were covered in green paint (*see figures 3 and 4*). The wooden panels used to create the wall were inconsistent in

size. The wall to the west seems to be covered with plaster. There is also a knee wall on the southern section of the room. The height of the knee measures to 35 3/8. The upper area between the door frame and knee wall is 45 inches. The wall boards near this knee are of various sizes. They range from 9 1/2 inches to 12 inches.



(Figure 3, attic wall)



(figure 4, attic wall)

Floor

The floor of the attic was covered with wooden floorboards that were of various sizes. It was difficult to determine the layout of the entire flooring due to some household items covering areas of the floor. The floorboard around the attics measure to 5 $\frac{3}{4}$ inches, with a $\frac{1}{2}$ inch top bead. There was also a seam in the flooring that measured to 20 $\frac{1}{2}$ inches in from the door opening that paralleled a seam in the south roof wall. The seams do not extend into the knee wall.

Door

The door (D-E-1) was missing from the entrance (*see figure 5*). The door frame measures to 33 $\frac{7}{8}$ X 72 $\frac{7}{8}$. It has a simply butt trim that measure to a width of 3 $\frac{5}{8}$ and has a hanging lock hinge on the frame with leather washers. In addition, the

door jam measures to 4 inches. The door itself is missing from the attic. A door that was placed on the northern side of the attic did not fit the door frame's measurements. Therefore, it is impossible that this door once belonged to the attic.



(Figure 5, door frame)