



EAST EXT.



NORTH EXT.


1 3/8" THICK



SOUTH EXT.

1 3/8" THICK


FRAME A - MOLDING AROUND DOOR PANEL = 1 1/2"
 FLAT FRAME SURROUND = 4 1/4"



DOOR A/B/C


Rm 101 Details

Fireplace



SW Window

6/6 panes




many panes replaced
No ropes/pullers

Nails?

* = wood block, milled lumber at top of window

NE Window

same as SW window except bottom panes replaced w/ 1 pane of glass




pane size =

1 1/2" w x 1 1/2" h

Muntins = 3/4"

Dabney-Scott-Adams House



- W corner ceiling to floor 9'
- N corner ceiling to floor 9'1 1/2"
- E corner ceiling to floor 9'1 1/2"
- S corner ceiling to floor 9'

Bowed plaster & lath on walls & ceiling

Chris + Lara
6-6-01

A. Curious door
(from Rm. 101)

B. Damaging ivy




SOUTH ELEVATION



EAST ELEVATION



WEST ELEVATION



ORIGINAL STANDING SEAM ROOF

- A. Deteriorating paint and plaster
- B. stucco finish pattern visible
- C. sample taken



EAST ELEVATION



- A. only raised panel door in the house (probably not original)
- B. door frame does not match others

101
NORTH WALL